

General Environmental Incident Summary

Incident: 3582 **Date/Time Notice:** 12/15/2014 15:10 **DEM Incident No:**

Responsible Party: Harvest States Cooperative

Date Incident: 12/15/2014 **Time Incident:** 14:00 **Duration:**

County: Burke **Twp:** 163 **Rng:** 90 **Sec:** 31 **Qtr:** SE

Lat: 48.89800 **Long:** -102.39400 **Method:** Interpolation from map

Location Description: Flaxton Railroad Corridor Lot 37: Located between SE Railroad St and the Soo Line railroad tracks and between NE Davis Ave. and 77th Ave. N.

Submitted By: Cindy Demers

Affiliation: Canadian Pacific

Address: 120 S. 6th St.

Suite 900

City: Minneapolis

State: MN

Zip: 55402

Received By:

Contact Person:

5500 Cenex Drive
Inver Grove Heights, MN 55077

Distance Nearest Occupied Building: 150 Feet **Release Contained:** Yes

Type of Incident: Unknown - Historical release

Description of Released Contaminant: Petroleum: GRO and DRO discovered in groundwater sample obtain 5 ft below grade surface

Volume Spilled:

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Unknown. Historical release. GRO and DRO reported in laboratory analysis of groundwater sample. Canadian Pacific leased the property to Harvest States Cooperative in 1980/90s. In 1998 Cenex and Harvest States joined and in 2003 CHS became their legal name.

Risk Evaluation:

No immediate risk identified.

of Fatalities:

of Injuries:

Affected Medium: 04 - water and soil

Potential Environmental Impacts:

GW impacts: GRO (670 ug/l) and DRO (1300 ug/l) at 5 ft bgs.

Soil Impacts: GRO (283 mg/l) sample obtained at 11-13 ft bgs (submerged)

Action Taken or Planned:

No planned activities. Canadian Pacific did not operate any facilities onsite. The site was leased to Harvest States Cooperative.

Wastes Disposal Location: N/A

Agencies Involved:

Updates

Date: 12/15/2014 **Status:** Reviewed - Assigned to NDDoH Division

Author: Roberts, Kris

Updated Volume:

Notes:

Discovery of historical fuel contamination at a railroad lease site in Flaxton. Referred to Division of Water Quality - Ground Water Program for followup.

Date: 4/13/2016 **Status:** Inspection

Author: Wax, Pete

Updated Volume:

Notes:

On site 12:05. Clear, 62 degrees, light wind from the SE, nearest water 1/4 mile to the east. Ground water issue. Called Carl Anderson (NDDoH, Groundwater Program), and he is taking over assessment and remediation of this site. Off site 12:25.